



Spill Characteristics and DNR Enforcement Efforts at Badger/Wolf/Brantley CAFO Complex, 1996–2021

SPILL AND ENFORCEMENT TOTALS

SPILL CHARACTERISTICS						MISSOURI DNR ENFORCEMENT EFFORTS				
Est. Volume of Reported Spills (gal.) ¹	Total Reported Spills	Reported Spills w/ Unknown Volume	% Spills w/ Unknown Volume	Avg. Spill Volume (gal.) ²	Avg. Annual Spill Volume, Past 30 Yrs. (gal.) ²	Letters of Warning	Notices of Violation	Spills w/o Onsite Response	% Spills w/o Onsite Response	Volume of Spills w/o Onsite Response (gal.) ¹
787,013	164	30	18%	5,873	26,234	2	2	103	63%	500,975

¹ These totals do not include reported spills of unknown volume. For details about spill calculation, see the Methodology section of the Rap Sheet (sraproject.org/SmithfieldMORapSheet)

² Average volumes were calculated for known spills (i.e., excluding spills of unknown volume).

BADGER/WOLF/BRANTLEY—REPORTED WASTE SPILLS AND VIOLATIONS

DATE	ESTIMATED GALLONS SPILLED	DESCRIPTION
9/19/1996	1,500	Agency records indicate a pipeline plugged with a dead piglet spilled wastes into emergency containment.
10/22/1996	1,000	Agency records indicate a plugged pipeline spilled into emergency containment.
1/4/1997	60,000	Agency records indicate a small dead pig plugged a waste pipeline that spilled into emergency containment.
1/5/1997	60,000	Agency records indicate three metal gate rods plugged a waste pipeline that spilled into emergency containment.
8/4/1997	3,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/14/1998	200	Agency records indicate a leaking pipeline spilled wastes into streambed. A crew built an emergency dam to contain the wastes. DNR did not respond on site to investigate the incident.
9/1/1998	1,500	Agency records indicate a backhoe cut a waste pipeline that spilled into the excavated trench.
9/25/1998	2,000	Agency records indicate a pump house pipeline failure spilled wastes into emergency containment.
2/28/1999	unknown	Agency records indicate a plugged pipeline flooded buildings with wastes and spilled into emergency containment.

8/10/1999	500–600	NOV #0677NE: On August 5, 1999, a leaking coupler clamp on an aluminum waste transport pipeline through a temporary public Township road culvert spilled wastes into the road right of way and onto a neighboring property. An emergency dam was constructed to contain the spill.
10/12/1999	15,000–20,000	Agency records indicate a plugged pipeline flooded buildings with waste and spilled into emergency containment.
12/6/1999	unknown	Agency records indicate a plugged pipeline backed up into buildings and spilled wastes into emergency containment.
4/4/2000	-----	<p>"NOV #0834NE: "Failure to Perform Stormwater Monitoring Within 24 Hours of Land Application"</p> <p>NOV #0835NE: "Failure to Report Other Chemicals Used at the Facility"</p> <p>NOV #0838NE: "Failure to Submit Accurate Discharge Monitoring Reports (DMRs) of the July 28, 1999, Discharge from Whitetail Facility"</p> <p>DMR Report on the 1999 Annual Records Review: "PSF failed to accurately report the required parameters from wastewater discharges as required by the existing permit. During a July 28, 1999, discharge of processed waste into Sandy Creek from the Whitetail facility, NERO [DNR Northeast Regional Office] staff collected samples for ammonia. The results of the NERO samples at the down gradient property boundary were nearly 500 times as high as those listed in the [company] report for the same day at the same sample location."</p> <p>Ten of eleven facilities reviewed were determined to be in noncompliance."</p>
8/25/2000	unknown	Agency records indicate wastes surfaced from a leaking underground pipeline. Waste spilled into a County gravel road right of way.
9/16/2000	unknown	Agency records indicate a plugged pipeline spilled wastes into emergency containment.
9/27/2000	unknown	Agency records indicate a plugged pipeline flooded buildings and then spilled wastes into emergency containment, "PSF to report all plugging incidents at this facility to evaluate concerns of sewer pipeline schematics."
10/11/2000	1,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment.
10/13/2000	unknown	Agency records indicate a plugged pipeline flooded a building with wastes, which exited the facility door and spilled into emergency containment.
11/25/2000	29,000	Agency records indicate that a wastewater spill was initially reported by PSF to be less than 1,000 gallons. DNR was notified three days later that the spill was estimated at 2,500 gallons, then later that afternoon it was estimated by PSF to be 29,000 gallons. DNR requested "PSF to evaluate/correct the piping system at this site, and also to evaluate spill estimates and reporting procedures."
1/18/2001	unknown	Agency records indicate a plugged pipeline flooded a nursery facility and wastes exited the structure before flowing into emergency containment.
2/8/2001	unknown	Agency records indicate a plugged pipeline backed up into the barn and wastes exited the structure before flowing into emergency containment.
3/14/2001	10,000	Agency records indicate a plugged pipeline to the lagoon spilled wastes into emergency containment. Wastes leaked through the emergency containment and into a waterway and an emergency dam was constructed to contain the spill.
4/10/2001	5,000–6,000	Agency records indicate a pipeline plug of unknown origin, possibly under a barn, caused wastes to back up into the birthing barn and spill into emergency containment.
6/10/2001	1,000	Agency records indicate a plugged pipeline backed up into the nursery barn and spilled wastes into emergency containment.
11/7/2001	>1,000	Agency records indicate a plugged pipeline between the barns and lagoon spilled wastes into emergency containment.
2/22/2002	3,000	Agency records indicate a plugged pipeline between the barns and a lagoon spilled wastes into emergency containment.

3/29/2002 unknown "Agency records indicate that DNR inspectors performed an Annual Review of facility records and documented that PSF "failed to accurately report sampling data at the Whitetail, Somerset, Green Hills and Badger/Wolf/Brantley facilities...failed to report the required information on the unauthorized discharge which occurred at the Whitetail facility on August, 2001...failed to report a fourth Stormwater Monitoring Event as required...for the following sites: Whitetail, South Meadows, Green Hills, Terre Haute, and Valley View...failed to report volumes and dates for the Somerset Facility of wastewater transported to other states...failed to provide the required information for two Outfalls [monitoring points], #20 and #27 at the Green Hills site...failed to sample and report Lake Monitoring at the Whitetail and Green Hills facilities in January and February of 2001...failed to report the land application information for the Brantley portion of the Badger/Wolf/Brantley Farm...failed to report monthly lagoon levels for the month of April at the Valley View site...failed to provide an annual summary of the required reporting information at the Water Treatment Plant (Outfall #42) at the Terre Haute Facility."

"The issue pertaining to the reporting of after cleanup results for discharge sampling is the most serious of the deficiencies identified in the review...It is imperative the sampling results reported are a true representation of the discharge prior to dilution or cleanup activities as specified in the permit...Future instances of reporting after cleanup results for discharges will be construed as noncompliance and will result in the department initiating the appropriated actions as deemed warranted."

10/11/2002	40,000	Agency records indicate a ruptured underground pipeline between the confinement barns and a lagoon spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
5/19/2003	>1,000	Agency records indicate a feed spill inside a plugged pipeline backed up wastes into a barn and spilled wastes into emergency containment.
10/14/2003	>1,000	Agency records indicate a plugged pipeline backed up into barn and spilled wastes into emergency containment.
2/15/2004	<1,000	Agency records indicate a plugged drain in a barn caused wastes to spill from the barn into emergency containment.
6/2/2004	<1,000	Agency records indicate a plugged pipeline caused wastes to spill from the nursery barn into emergency containment.
9/25/2004	2,500	Agency records indicate a plugged pipeline between a barn and a lagoon spilled into emergency containment. DNR did not respond on site to investigate the incident.
1/13/2005	1,000	Agency records indicate a plugged pipeline in a hog barn spilled wastes into emergency containment.
1/27/2005	4,000	Agency records indicate a plugged pipeline between a barn and lagoon spilled wastes into a stormwater diversion channel.
4/22/2005	>1,000	Agency records indicate a plugged pipeline between three barns and the lagoon spilled wastes from the barns into emergency containment.
10/18/2005	1,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency dams. DNR did not respond on site to investigate the incident.
11/26/2005	>1,000	Agency records indicate a plugged pipeline spilled wastes from two barns into emergency containment.
5/2/2006	10,000	Agency records indicate a plugged pipeline between the barns and lagoon spilled wastes into emergency containment. The emergency containment system failed to capture other portions of the spill, which were contained on the facility.
6/28/2006	>1,000	Agency records indicate a plugged pipeline between two barns and the lagoon backed up into a barn and spilled wastes into emergency containment.
10/11/2006	1,500	Agency records indicate a plugged pipeline spilled wastes into emergency containment.

12/7/2006	2,000	Agency records indicate a plugged pipeline between a nursery barn and the lagoon spilled wastes into emergency containment.
12/27/2006	>1,000	Agency records indicate a plugged pipeline between a barn and the lagoon spilled wastes into emergency containment.
2/13/2007	1,000	Agency records indicate a plugged pipeline between the nursery barn and lagoon spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/2/2007	500	Agency records indicate that a waste pipeline irrigation riser spilled wastes into a shallow ditch on company property. An emergency dam was constructed to contain the spill
4/25/2007	unknown	Agency records indicate a plugged pipeline from a barn to the lagoon spilled wastes into emergency containment.
8/16/2007	>2,000	Agency records indicate a plugged pipeline spilled wastes from the Mega Nursery barn into emergency containment.
10/12/2007	>1,000	Agency records indicate a broken pipeline between the barns and lagoon spilled wastes into emergency containment.
10/29/2007	1,200–1,300	Agency records indicate a plugged pipeline spilled wastes from a barn over a road and into emergency containment. A hole in the emergency containment pipeline allowed wastes to bypass the containment system. Two emergency dams were constructed to contain the spill. The company's initial report to DNR claimed that the wastes had been confined to its emergency containment system.
11/12/2007	2,000	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
1/2/2008	unknown	Agency records indicate a plugged pipeline spilled wastes from the gestation and nursery barn into emergency containment. DNR did not respond on site to investigate the incident.
9/27/2008	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment.
11/1/2008	25	Agency records indicate a manure tank truck had a mechanical failure and spilled wastes onto a gravel road. DNR did not respond on site to investigate the incident.
2/17/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment.
4/27/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
5/11/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment.
5/14/2009	unknown	Letter of Warning: Agency records indicate a plugged pipeline spilled wastes into emergency containment. A second spill occurred the evening of May 18. "The second release was reportedly less than 1,000 gallons and is not required to be reported to the Department." Wastes were observed leaking through the emergency containment system.
5/31/2009	1,000	Agency records indicate a plugged pipeline in cell 9A spilled wastes that were captured with temporary emergency dams before reaching the emergency containment system. DNR did not respond on site to investigate the incident.
6/4/2009	15,000	Agency records indicate a plugged barn pipeline spilled wastes into emergency containment. An emergency dam was constructed to help contain the spill.
6/26/2009	1,000	Agency records indicate a pipeline burst during land application and spilled wastes into the right of way of County Road O. Wastes flowed back onto company property and into a pond.
6/28/2009	500	Agency records indicate overapplication and runoff during land application on Field 520 spilled wastes into a pond on Field 518.

7/11/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
7/23/2009	1,100	Agency records indicate a broken pipeline inside of a barn spilled wastes into emergency containment.
9/27/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
9/28/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a gestation barn into emergency containment. DNR did not respond on site to investigate the incident.
11/10/2009	1,000	Agency records indicate a plugged pipeline leading from the gestation barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
11/23/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
12/10/2009	unknown	Agency records indicate a plugged pipeline at a nursery barn spilled wastes that froze in place before reaching the emergency containment system. DNR did not respond on site to investigate the incident.
12/18/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
12/28/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
12/30/2009	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
1/12/2010	unknown	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
3/12/2010	2,500	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
3/14/2010	3,000	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
5/13/2010	5,000	Agency records indicate a plugged pipeline spilled wastes from a birthing barn into emergency containment. DNR did not respond on site to investigate the incident.
5/28/2010	5,000	Agency records indicate a broken pipeline inside of an irrigation pump house spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
5/29/2010	1,200	Agency records indicate a plugged pipeline at a nursery barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
6/5/2010	unknown	Agency records indicate heavy rains filled a lagoon and its emergency containment system and spilled wastes into a stream. Sandbags were placed in the lagoon spillway to slow the spill; dirt was also added behind the sandbags.
6/8/2010	1,000	Agency records indicate a pipeline riser was left uncapped in Field 49 during a waste transfer and spilled wastes into a drainageway. Three emergency dams were constructed to contain the spill.
7/2/2010	1,000	Agency records indicate a hay mower hit an irrigation riser and spilled wastes into Field 24. DNR did not respond on site to investigate the incident.
7/12/2010	1,000	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
7/15/2010	1,000	Agency records indicate overapplication and runoff on Field 4 spilled wastes into a small stream on company property. An emergency dam was constructed to contain the spill

7/26/2010	3,638	Agency records indicate a manure tank wagon overturned on a gravel road and spilled some of its contents onto land application Field 508. Multiple emergency dams were constructed to contain the spill.
8/1/2010	5,000	Agency records indicate an underground pipeline separated during a waste transfer between lagoons and surfaced. Wastes traveled toward the emergency containment system, which captured approximately 200 gallons of the spill. DNR did not respond on site to investigate the incident.
8/7/2010	1,500	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
8/21/2010	4,000	Agency records indicate a broken pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
9/11/2010	5,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
9/17/2010	3,000	Agency records indicate a broken pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
12/9/2010	20,000	Agency records indicate that the company reported a plugged pipeline in a birthing barn spilled wastes into emergency containment; DNR investigators found that in fact two spills had actually occurred; the second spill was due to a plugged pipeline in a gestation barn.
12/9/2010	3,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment.
12/20/2010	5,000	Agency records indicate a plugged pipeline spilled wastes from a barn into emergency containment. DNR did not respond on site to investigate the incident.
1/31/2011	1,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/6/2011	20,000	Agency records indicate a broken cleanout riser in an underground pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/7/2011	-----	Agency records indicate that a barn fire damaged a nursery barn. The barn was considered a total loss and was demolished. An asbestos inspector wrote, "Several hundred pigs burned up in this fire and the owner needs to dig a trench through this barn to provide utilities to another barn to house additional pigs that are currently being housed without heat or water. Consequently, the owner is requesting an emergency waiver of the 10 days business rule."
2/17/2011	1,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/22/2011	10,000	Agency records indicate a leaking pipeline riser spilled wastes into Field 47 during a lagoon transfer. An emergency dam was constructed to contain the spill.
3/8/2011	5,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/21/2011	2,000	Agency records indicate an underground pipeline from a barn broke and spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/29/2011	3,000	Agency records indicate a plugged pipeline spilled wastes from a barn. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
4/8/2011	10,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/20/2011	1,000	Agency records indicate a plugged pipeline and a broken underground pipeline spilled wastes from a barn. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.

4/20/2011	5,000	Agency records indicate a broken pipeline at a birthing barn spilled wastes into two emergency containments. While pumping the wastes back to the lagoon, a pipeline broke. The lagoon's contents were being lowered five feet to repair a waste pipeline. The company reported that the spill was still occurring so the initial estimate of spilled wastes would increase. DNR did not respond on site to investigate the incident.
4/22/2011	1,000	Agency records indicate a plugged pipeline spilled wastes from a barn. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
5/27/2011	2,000	Agency records indicate a plugged pipeline in Barn B spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
6/2/2011	1,000	Agency records indicate a plugged pipeline spilled wastes from a barn. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
6/3/2011	-----	Agency records indicate a DNR inspector documented, "Dead pigs were observed floating in some of the lagoons. The mortality station was observed. A semi dump trailer was observed at the transfer station location. The open top trailer was nearly full of dead hogs." DNR made the following recommendations: "Ensure that feed spills are removed and properly disposed when discovered. Ensure that trash is removed from the lagoons as discovered and properly disposed. Evaluate the cause of recent pipe blockages, and determine possible actions necessary to prevent additional blockages in the future. Ensure the semi-trailers used to collect dead animals are removed from the site each day."
7/8/2011	1,000	Agency records indicate a plugged pipeline spilled wastes. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
7/14/2011	5,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
7/21/2011	3,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
8/26/2011	2,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
10/20/2011	3,000	Agency records indicate a spill from a nursery barn allegedly soaked into the ground. DNR did not respond on site to investigate the incident.
11/18/2011	1,500	Agency records indicate a plugged pipeline spilled wastes from behind Barn #1. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
1/27/2012	1,000	Agency records indicate a plugged pipeline in a gestation barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/1/2012	2,000	Agency records indicate a plugged pipeline in a breeding barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/26/2012	3,000	Agency records indicate a plugged pipeline in Barn G spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/28/2012	-----	Agency records indicate a DNR Annual Records Review of PSF records noted that the company failed to report the suspected causes of high ammonia readings [indicative of hog waste] in the company's emergency containment systems as required by their Missouri State Operating Permits. Nine facilities were determined to be in noncompliance.
5/4/2012	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
10/6/2012	10,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.

4/2/2013	unknown	Agency records indicate a plugged pipeline in barn G and an underground pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/6/2013	3,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/16/2013	30,000	Agency records indicate a broken underground pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/29/2013	2,000	Agency records indicate a crew was working to unplug a pipeline when wastes spilled from a broken cleanout riser into emergency containment. DNR did not respond on site to investigate the incident.
5/8/2013	15,000	Agency records indicate a spill of wastes into emergency containment. No cause is listed in DNR's spill database. DNR did not respond on site to investigate the incident.
5/31/2013	5,000	Agency records indicate an aboveground hose spilled during a waste transfer. An emergency dam was constructed to contain the spill. DNR did not respond on site to investigate the incident.
6/27/2013	5,000	Letter of Warning: Agency records indicate that on June 13, 2013, an underground pipeline broke in Field 4 and spilled wastes into a tributary of Little Medicine Creek. An emergency dam was constructed to contain the spill.
7/7/2013	1,500	Agency records indicate a break in a pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
7/11/2013	2,500	Agency records indicate a leaking pipeline riser spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
11/3/2013	1,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
1/11/2014	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
1/29/2014	3,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/24/2014	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/27/2014	13,000	Agency records indicate a joint separation in an underground pipeline spilled into emergency containment. DNR did not respond on site to investigate the incident.
2/27/2014	13,000	Agency records indicate a broken pipeline between the barns and lagoon spilled wastes into secondary containment. DNR did not respond on site to investigate the incident.
3/12/2014	1,200	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/25/2014	3,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/7/2014	5,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/30/2014	1,200	Agency records indicate a plugged pipeline in a barn spilled wastes that soaked into the ground near the facility. DNR did not respond on site to investigate the incident.
5/3/2014	1,150	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
5/6/2014	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
5/16/2014	1,000	Agency records indicate a plugged pipeline in a barn spilled wastes that were contained by excavations before reaching the emergency containment system. DNR did not respond on site to investigate the incident.

6/9/2014	10,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
6/11/2014	1,000	Agency records indicate a plugged pipeline backed up into a barn and spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
6/23/2014	2,500	Agency records indicate a spill of wastes into emergency containment. No cause is listed in DNR's spill database. The database states, "Under the conditions of the permit any release beyond 1,000 gallons is a reportable event." DNR did not respond on site to investigate the incident.
10/23/2014	150,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
10/29/2014	unknown	Agency records indicate overapplication and runoff of land-applied wastes in Field 62 spilled into a tributary of Barber Creek and emergency dams and trenches were constructed to contain the spill. The facility was determined to be in noncompliance.
11/20/2014	-----	Agency records indicate a DNR inspector recommended that feed spills be removed and properly disposed when discovered, trash be removed from the lagoons as discovered and properly disposed, and building debris be removed from the lagoon at Badger #6 and properly disposed of.
11/21/2014	3,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
11/26/2014	1,000	Agency records indicate a plugged pipeline in a barn spilled wastes that were contained by an emergency dam before reaching the emergency containment system. DNR did not respond on site to investigate the incident.
12/6/2014	5,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
12/6/2014	5,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
12/8/2015	2,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/12/2016	3,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
3/31/2016	2,000	Agency records indicate either a broken pipeline or a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/2/2016	2,000	Agency records indicate wastes spilled into emergency containment. No cause is listed in DNR's spill database. DNR did not respond on site to investigate the incident.
4/18/2016	1,500	Agency records indicate wastes spilled into emergency containment. No cause is listed in DNR's spill database. DNR did not respond on site to investigate the incident.
5/23/2016	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
5/27/2016	3,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
7/12/2016	-----	Agency records indicate a DNR inspector noted, "Remove the trees from the lagoon berms at Brantley Sow and Brantley Finish. Ensure feed spills are routinely cleaned up and properly managed. Remove trash from the lagoon at Badger 8."
12/4/2016	1,000	Agency records indicate a plugged pipeline spilled wastes. An emergency dam was constructed and contained the spill before it reached the emergency containment system. DNR did not respond on site to investigate the incident.
12/13/2016	1,500	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
1/17/2017	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
1/21/2017	2,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.

2/3/2017	2,000	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/7/2017	3,000	Agency records indicate a spill into emergency containment. No cause is listed in DNR's spill database. DNR did not respond on site to investigate the incident.
2/12/2017	5,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/14/2017	1,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/15/2017	2,500	Agency records indicate a plugged pipeline spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
2/16/2017	1,000	Agency records indicate a plugged pipeline in a barn spilled wastes into emergency containment. DNR did not respond on site to investigate the incident.
4/19/2017	-----	Agency records indicate a DNR inspector noted, "Ensure that dead pigs are removed from the lagoons and properly disposed when discovered. Ensure that feed spills are removed and properly disposed when discovered. Ensure that trash is removed from the lagoons as discovered and properly disposed."
10/25/2017	-----	Agency records indicate a DNR inspector noted, "Spilled feed was observed at Brantley Sow, Badger #1 and Badger #5. Please ensure spilled feed is cleaned up and properly managed as soon as practicable. Three lead acid batteries were observed under feeder #1990 at Wolf 3. Please ensure the batteries are removed and properly managed and recycled."
8/4/2020	unknown	Agency records indicate a DNR inspector recommends blood spillage at the mortality transfer station is minimized, and also recommends the removal of woody vegetation at Wolf #1.
8/4/2020	unknown	Agency records indicate a DNR inspector noted, "Ensure that feed spills are removed and properly disposed when discovered. Ensure that the blood spillage at the mortality transfer is minimized and a discharge does not occur."
10/15/2020	-----	Agency records indicate a DNR inspector noted, "Ensure that feed spills are removed and properly disposed when discovered. Fill in ruts in lagoon spillway at Mega."
2/25/2021	-----	Agency records indicate a DNR inspector noted, "Ensure that feed spills are removed and properly disposed when discovered. Ensure that trash is removed from the lagoons as discovered and properly disposed."